

## **Wind Mitigation Feature Documentation Guidelines**

The chart below provides examples of documentation that you or your agent can provide to a Citizens inspector or submit to Citizens to help verify wind mitigation features on your property. Documentation must show clearly that wind mitigation features meet the standards to receive credits established by the Florida Office of Insurance Regulation on the most recent version of the *Uniform Mitigation Verification Inspection Form* (OIR-B1-1802). All documentation submitted to substantiate the existence of wind mitigation features is subject to review and approval by Citizens.

Feature	Common Reasons for Credit Removal	<b>Common Documentation Examples</b>	How to Request Credit Reapplication
Roof Covering	<ul> <li>Does not meet Florida Building Code year-built requirements:         <ul> <li>If the property is located in Miami-Dade or Broward counties, the roof permit application must be dated 9/1/1994 or later</li> <li>If in any other county, the property's roof permit application must be dated 3/1/2002 or later</li> </ul> </li> <li>Unable to verify roof was replaced using applicable building code</li> <li>The current version of the OIR-B1-1802 requires updated information for the entire roof, not just the predominant roof covering</li> </ul>	<ul> <li>Permit information</li> <li>Paid-in-full roof contracts and/or invoices documenting when the roof was replaced or installed</li> </ul>	If the inspector is unable to obtain permit information, you can provide:
Roof-Deck Attachment (underside of your roof that is visible in your attic)	<ul> <li>No attic access</li> <li>Insulation blocking features</li> <li>Items blocking attic openings and/or features</li> <li>Nail size and nail spacing requirements not met</li> <li>Use of other attachments besides nails (adhesives, staples, etc.)</li> </ul>	<ul> <li>Clear photos from a prior retail inspection</li> <li>Blueprints with nailing pattern details provided</li> </ul>	If the inspector is unable to gain attic access or view features, you can:  Provide blueprints showing nails and nail spacing and patterns  Provide clear photos from a prior retail inspection documenting the feature clearly  Create access to the attic and order a free 2 <sup>nd</sup> inspection to have another inspector validate the features
Roof-to-Wall Connection (the areas where the exterior walls of your home connect to	<ul> <li>No attic access</li> <li>Insulation blocking features</li> <li>Items blocking attic openings and/or features</li> <li>Nail pattern requirement not met</li> <li>Use of other attachments (plumbing straps)</li> <li>The current version of the OIR-B1-1802 provides specific minimum nailing requirements; for example, single wraps and</li> </ul>	<ul> <li>Blueprints – If nailing pattern details provided</li> <li>Clear photos from a prior retail inspection</li> </ul>	If the inspector is unable to gain attic access or view features, you can:  Provide blueprints showing clear details of attachments used including nailing pattern  Create access to the attic and order a free 2 <sup>nd</sup> inspection to have another inspector validate the features

Feature	Common Reasons for Credit Removal	Common Documentation Examples	How to Request Credit Reapplication
the roof)	clips must have a minimum of three nails		
Roof Geometry (shape)	<ul> <li>Roof is not hip</li> <li>The current version of the OIR-B1-1802, added 10 percent rule to qualify for hip credit. No other roof shape can be greater than 10 percent</li> <li>If the non-hip portion is greater than 10 percent and structurally connected, it is considered the weakest point</li> </ul>	<ul> <li>Clear photos</li> <li>Calculation of roof perimeter versus total square footage</li> </ul>	Provide documentation that confirms the total perimeter of your roof is hip with no other roof shapes (gable, flat areas, etc.) making up 10 percent or more of the total perimeter
Secondary Water Resistance (SWR)	<ul> <li>Unable to verify</li> <li>Spray foam insulation products do not qualify</li> </ul>	Paid-in-full contracts and/or invoices showing SWR applied during re-roofing	Provide one or more of the following:  Paid-in-full contracts and/or invoices showing SWR applied during re-roof  Photos showing SWR being applied  Proof of FoamSeal being installed
Opening Protection	<ul> <li>Not all openings protected</li> <li>Not impact-rated</li> <li>Unable to verify impact rating</li> <li>No Miami-Date stamp</li> <li>New Citizens rule changed the rating related to wood panels taking away the C-Credit</li> <li>Shutters not on premises</li> </ul>	Notice of Acceptance or FL Product approval documents     Final permit information – depending on county/city	Provide one or more of the following:  Notice of Acceptance or FL Product approval documents. These are generally provided by the product manufacturer or installer  Receipts with product numbers included Photo of window etching or product information
Building Construction	<ul> <li>Frame construction of more than 33.3 percent of total construction</li> <li>Gable ends are included in wall construction calculations</li> <li>Second story is typically frame construction</li> </ul>	<ul> <li>Appraisals done by a licensed property appraiser</li> <li>Blueprints showing construction</li> <li>Clear photos of top plate/bond beam in attic</li> </ul>	Provide one or more of the documents noted

Feature	Common Reasons for Credit Removal	Common Documentation Examples	How to Request Credit Reapplication
Year Built	<ul> <li>Property appraiser determined the year of construction to be prior to January 1, 2002</li> <li>Permit information confirmed year built prior to January 1, 2002</li> </ul>	<ul> <li>Permit information</li> <li>Property card from the property appraiser office</li> <li>Certificate of occupancy</li> </ul>	Provide permit, certificate of occupancy or property card confirming year built January 1, 2002 or later